

DISCOM : BYPL

OUTAGE REPORT FOR:06:00 HRS. OF 05.08.2018 TO 06:00 HRS OF 06.08.2018

Sr. No.	Date	Division	Start Time	End Time	Duration	Reason for Outage		Action	Main Area affected	No. of consumer affected	Remarks
							Details				
1	05.08.2018	DGN	17:48	19:43	01:54	LT FEEDER	TO ATTEND FAULT IN THE CIRCUIT	LTAB BURNT DUE TO FIRE, SAME REPAIRED	JHILMIL INDUSTRIAL AREA BLOCK A-JHILMIL COLONY.	9	
2	05.08.2018	KWN	13:43	15:56	02:12	HVDS CABLE & OTHER SYSTEM	TO ATTEND FAULT IN THE CIRCUIT	HVDS CABLE END BOX DAMAGED, SAME REPAIRED	D2 SONIA VIHAR,KARAWAL NAGAR.	3994	HVDS CABLE END BOX DAMAGED, SAME REPAIRED AT D2 SONIA VIHAR
3	05.08.2018	KWN	18:58	21:12	02:14	HT SYSTEM FAULT	TRIPPING	RMU BUSHING FOUND DAMAGED, SAME BYPASSED	SHIV VIHAR PHASE-1,KARAWAL NAGAR.	432	RMU BUSHING FOUND DAMAGED, SAME BYPASSED AT S/STN SHIV VIHAR PHASE 1
4	05.08.2018	KWN	21:19	22:34	01:15	HVDS CABLE & OTHER SYSTEM	TO ATTEND FAULT IN THE CIRCUIT	HVDS LEAD FAULTY, SAME REPAIRED	BLOCK D-OLD MUSTAFABAD,BLOCK R-PATEL VIHAR.	1981	
5	05.08.2018	KWN	21:42	23:14	01:31	FORCE MAJEURE (RAIN/WATER LOGGING/STORM, ETC.)	TRIPPING	DUE TO HEAVY RAIN TRANSFORMER DD FUSE BLOWN, SAME REPLACED	BLOCK J-SHIV VIHAR,NON COMM AREA-SONIA VIHAR.	3236	
6	05.08.2018	VSE	19:40	21:00	01:19	HT SYSTEM FAULT	TRIPPING	HT PANEL FOUND FLASHED, SAME REPAIRED	BLOCK_G1/A-KONDALI GHAROLI,COMMUNITY CENTER.	257	