

DISCOM : TATA Power-DDL

OUTAGE REPORT FOR : 05-08-2018

Sr. No.	Date	Division	Start Time	End Time	Duration	Reason for Outage		Action	Main Area affected	No. of consumer affected	Remarks
						Main Reason	Details				
1	5-Aug-2018	Shalimar Bagh	12:26	13:43	01:17	HT SYSTEM FAULT	HT Jumper Burnt	Restored/Repaired	Parts of : I.P Colony	1565	Interruption due to fault
2	5-Aug-2018	Badli	00:48	02:00	01:12	HT SYSTEM FAULT	Birdage	Restored/Repaired	Part of : Sector - 26 Rohini	727	Interruption due to fault
3	5-Aug-2018	Model Town	02:36	04:05	01:29	DISTRIBUTION TR.	DD Jumper Burnt	Restored/Repaired	Parts of : Naniwala Bagh	486	Interruption due to fault
4	5-Aug-2018	Narela	04:07	05:20	01:13	HVDS CABLE & OTHER SYSTEM	HT ABC Burnt	Restored/Repaired	Parts of : Singhu Village	1122	Interruption due to fault
5	5-Aug-2018	Shalimar Bagh	07:46	10:50	03:04	FORCE MAJEURE (RAIN/WATER LOGGING/STORM, ETC.)	External Item Fell on Line	Restored/Repaired	Part of : C Block Jahangir Puri	1821	Force majeure due to sabotage
6	5-Aug-2018	Narela	08:40	10:35	01:55	HT SYSTEM FAULT	Birdage	Restored/Repaired	Part of : Nangali Poona	1671	Interruption due to fault
7	5-Aug-2018	Model Town	10:57	13:25	02:28	FORCE MAJEURE (RAIN/WATER LOGGING/STORM, ETC.)	Tripping due to Kite String	Restored/Repaired	Part of : Adarsh Nagar	4332	Force majeure due to sabotage
8	5-Aug-2018	Shalimar Bagh	12:40	13:50	01:10	HT SYSTEM FAULT	HT Jumper Burnt	Restored/Repaired	Part of : H Block Jahangir Puri	683	Interruption due to fault
9	5-Aug-2018	Shalimar Bagh	13:09	14:35	01:26	HT SYSTEM FAULT	HT Jumper Burnt	Restored/Repaired	Part of : Bhalswa Village	6474	Interruption due to fault
10	5-Aug-2018	Bawana	13:36	15:10	01:34	HT SYSTEM FAULT	Pin Insulator Flashed	Restored/Repaired	Part of : Agar Nagar	2925	Interruption due to fault
11	5-Aug-2018	Narela	14:35	19:42	05:07	DAMAGE BY OTHER AGENCIES	HT Pole Damaged by Unknown Vehicle	Restored/Repaired	Part of : Kadi Pur	2699	Force majeure due to sabotage
12	5-Aug-2018	Mangol Puri	16:10	18:03	01:53	HVDS CABLE & OTHER SYSTEM	HT Cable Faulty	Restored/Repaired	Part of : Aman Vihar	2002	Interruption due to fault
13	5-Aug-2018	Mangol Puri	16:18	18:15	01:57	HVDS CABLE & OTHER SYSTEM	HT ABC Burnt	Restored/Repaired	Part of : Nithari Village	841	Interruption due to fault
14	5-Aug-2018	Bawana	18:04	20:20	02:16	FORCE MAJEURE (RAIN/WATER LOGGING/STORM, ETC.)	Tripping due to Kite String	Restored/Repaired	Part of : Auchandi Village	3232	Force majeure due to sabotage
15	5-Aug-2018	Bawana	18:18	19:30	01:12	HT SYSTEM FAULT	HT Jumper Burnt	Restored/Repaired	Part of : Karala Village	445	Interruption due to fault

Sr. No.	Date	Division	Start Time	End Time	Duration	Reason for Outage		Action	Main Area affected	No. of consumer affected	Remarks
						Main Reason	Details				
16	5-Aug-2018	Narela	18:51	20:12	01:21	HT SYSTEM FAULT	CT / PT Unit Flashed	Restored/Repaired	Part of : Khera Kalan	3980	Interruption due to fault
17	5-Aug-2018	Narela	18:55	21:32	02:37	FORCE MAJEURE (RAIN/WATER LOGGING/STORM, ETC.)	Tree Branch Fell on Line	Restored/Repaired	Parts of : Lampur Village	1698	Force majeure due to sabotage
18	5-Aug-2018	Badli	19:15	20:25	01:10	HVDS CABLE & OTHER SYSTEM	HT ABC Sparking	Restored/Repaired	Part of : Rajeev Nagar	573	Interruption due to fault
19	5-Aug-2018	Mangol Puri	08:56	10:50	01:54	HT SYSTEM FAULT	HT Jumper Sparking	Restored/Repaired	Part of : Pooth Kalan	1421	Interruption due to fault
20	5-Aug-2018	Mangol Puri	14:37	17:55	03:18	DAMAGE BY OTHER AGENCIES	HT Cable Damaged by External Agency	Restored/Repaired	Part of : Laxmi Vihar	3182	Force majeure due to sabotage
21	5-Aug-2018	Mangol Puri	13:55	16:38	02:43	FORCE MAJEURE (RAIN/WATER LOGGING/STORM, ETC.)	Tree Branch Fell on Line	Restored/Repaired	Part of : Krishna Vihar	1677	Force majeure due to sabotage
22	5-Aug-2018	Mangol Puri	16:11	18:05	01:54	HT SYSTEM FAULT	Cat Electrcution	Restored/Repaired	Part of : Budh Vihar	2253	Interruption due to fault
23	5-Aug-2018	Mangol Puri	16:46	17:58	01:12	HT SYSTEM FAULT	Birdage	Restored/Repaired	Part of : Sector - 20 Rohini	4984	Interruption due to fault
24	5-Aug-2018	Moti Nagar	00:02	01:30	01:28	LT FEEDER	LT Jumper Burnt	Restored/Repaired	Part of : Ranjit Nagar	665	Interruption due to fault
25	5-Aug-2018	Shalimar Bagh	03:21	05:10	01:49	LT FEEDER	LT Cable Faulty	Restored/Repaired	Part of : Burari Village	707	Interruption due to fault
26	5-Aug-2018	Shalimar Bagh	03:43	05:40	01:57	LT FEEDER	Tyco Box Burnt	Restored/Repaired	Part of : Bengali Colony	354	Interruption due to fault